



Explanation

- Raton property boundary
- Lake Maloya drainage area
- Stream
- Fire severity
 - Unchanged / very low
 - Low severity
 - Moderate severity
 - High severity

Note: Severity data from U.S. Forest Service (2011).

S:\PROJECTS\WR08.0177_2008-2009_SUGARITE_RESTORATION_OVERSIGHT\GIS\MXDS\TRACK_FIRE_BARCBURN_SEVERITY.MXD 11/2/8



Daniel B. Stephens & Associates, Inc.
 8/2/2011 JN WR11.0169

SUGARITE WATERSHED
Track Fire Area Burn Severity